UL Product iQ™

ECBT2.E304945 - Connectors for Use in Data, Signal, Control and Power Applications - Component

Note: We are enhancing our systems and you may notice duplicate entries/missing/outdated data. During this interim period, please contact our Customer Service at https://www.ul.com/about/locations.

Connectors for Use in Data, Signal, Control and Power Applications - Component

HONGRU CONNECTOR CO LTD E304945
1 XIJIE ZHENYUAN RD
CAIWU INDUSTRIAL AREA WUSHA
CHANGAN TOWN
DONGGUAN, GUANGDONG 523857 China

Marking: Company name or tradename "HRB" , "HRBCN" , "HRBCONN" , and model designation.
Note: For additional marking information, refer to the Guide Information Page.

Model(s): P1300-7-N, P1310-7-N, P2030-1-N, P2130-1-N

Model(s): A-M63501 followed by WF, followed by -1x, followed by 2 thru 4, followed by –W, -G, -B.

Model(s): A-M63502 followed by WF, followed by -1x, followed by 2 thru 4, followed by –W, -G, -B.

Model(s): M20032 followed by E or blank, followed by -1x, followed by 2 thru 4, followed by –W, -G, -B.

Model(s): M20033 followed by E or blank, followed by -1x, followed by 2 thru 4, followed by –W, -G, -B.

Model(s): M5001 followed by -02 thru -12, followed by -A or -B, followed by -0 thru -11, followed by -W, -b, -G, -B, -R.

Model(s): M5002 followed by -02 thru -12, followed by -W, -b, -G, followed by -000 thru -1200, followed by -00 or -A0 to -K9, followed by -A or -B, followed by blank, 00H, 02H, 03H, 15H, 20H, 30H or -s, followed by (0) or (8).

Model(s): M7500 followed by -2 thru -10, followed by -0000 thru -9999

Model(s): M7501 followed by -2 thru -10, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -9, followed by -BLANK, -S, -00H, -02H or -03H

Model(s): M9400 followed by -02 thru -12, followed by -000 thru -1200, followed by -00 or -A0 to -K9, followed by blank, 00H, 02H, 03H, 15H, 20H, 30H or -S.

Model(s): M9401 followed by -02 thru -12, followed by -000 thru -1200, followed by -00 or -A0 to -K9, followed by blank, 00H, 02H, 03H, 15H, 20H, 30H or -S.

Model(s): M9402 followed by -02 thru -12, followed by -000 thru -1200, followed by -00 or -A0 to -K9, followed by blank, 00H, 02H, 03H, 15H, 20H, 30H or -S.

Model(s): M9403 followed by -02 thru -12, followed by -000 thru -1200, followed by -00 or -A0 to -K9, followed by blank, 00H, 02H, 03H, 15H, 20H, 30H or -S.

Model(s): M9406 followed by -02 thru -12, followed by -000 thru -1200, followed by -00 or -A0 to -K9, followed by blank, 00H, 02H, 03H, 15H, 20H, 30H or -S.

Model(s): M9848 followed by -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -3x2, -3x3, -3x4 or -3x5, followed by -W, followed by D, followed by (M) or (F)

Model(s): P2030 followed by -1x1, -1x2, -1x3, -1x4, -2x3 or -3x3, followed by -N, followed by -DL

Model(s): P3020 followed by -1x2, -1x3, -1x4, -2x1, -2x2, -2x3, -2x4, followed by -GWTK, followed by -K.

Model(s): P3025 followed by -1x2, -1x3, -1x4, -2x1, -2x2, -2x3, -2x4, followed by -GWTK, followed by -K.

Model(s): P5008 followed by -2 thru -8, followed by -W, -B, -N, -b or -G, followed by -000 thru -1200, followed by -00

Model(s): P5010 followed by -2 thru -8, followed by -W, -B, -N, -b or -G, followed by -000 thru -1200, followed by -00 or -A0 to -K9

Model(s): P5011 followed by -2 thru -8, followed by -W, -B, -N, -b or -G, followed by -000 thru -1200, followed by -00 or -A0 to -K9.

Model(s): P5012 followed by -2 thru -8, followed by -W, -B, -N, -b or -G, followed by -000 thru -1200, followed by -00 or -A0 to -K9.

Model(s): P63503 followed by -1x, followed by 2 or 3, followed by followed by –W, -G, -B.

Model(s): P63504 followed by WF, followed by -1x, followed by 2 thru 4, followed by –W, -G, -B.

Model(s): P70921 followed by -1 thru -12, followed by -W

Model(s): P70922 followed by -2 thru -12, followed by -W

Model(s): P70923 followed by -1 thru -12, followed by -W

Connectors, Model(s): Cat. No. P2509-8-08., Cat. No. P42475-2x3-C, Cat. Nos. M5601-2-O and M5602-2-O, M7060(I)-20, M7060(I)-20R, M7060(I)R-20, M7060(I)R-20R

Connectors, Model(s): Cat. No. M72, followed by 90, followed by -7, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -7, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): Cat. No. M7238, followed by R or blank, followed by -2 thru -20, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Connectors, Model(s): Cat. No. M7239, followed by R or blank, followed by -2 thru -20, followed by -A or -B, followed by A or B, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Connectors, Model(s): Cat. Nos. M7234, followed by -2 thru -20, followed by -0000 thru -9999, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Connectors, Model(s): Cat. Nos. M7234R, followed by -2 thru -20, followed by -0000 thru -9999, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Connectors, Model(s): M2002 , followed by -2 thru -15, followed by -W, -B or -G,P1020, followed by -1x2, -1x3, -2x2, -2x3, -2x4, -2x5, -2x6, -2x7, -2x8, -2x9, -2x10, -2x11, -2x12, -3x3, -followed by -N or -W, followed by -H-A.

Connectors, Model(s): M20021 , followed by R or blank, followed by -02 thru -15, followed by -W or -B

Connectors, Model(s): M2040-2 thru M2040-14 followed by -2 thru -24, followed by -R, -O, -W, -Y, -N or -B, followed by -R, -P or blank

Connectors, Model(s): M2040-2-b thru M2040-14-b followed by -2 thru -14, followed by -R or -b

Connectors, Model(s): M2040-2-R thru M2040-14-R followed by -2 thru -14, followed by -R or -b

Connectors, Model(s): M2050 followed by -2 thru -20, followed by -R, -Y, -W, -b, -B or -G, followed by -R or blank

Connectors, Model(s): M2051-2 thru M2051-17 followed by -2 thru -17, followed by blank, -R or -P

Connectors, Model(s): M2051-2-P thru M2051-17-P followed by -2 thru -17, followed by blank, -R or -P

Connectors, Model(s): M2051-2-R thru M2051-17-R followed by -2 thru -17, followed by blank, -R or -P

Connectors, Model(s): M2051R-2 thru M2051R-24 followed by -2 thru -24, followed by blank, -R or -P

Connectors, Model(s): M2051R-2-P thru M2051R-24-P followed by -2 thru -24, followed by blank, -R or -P

Connectors, Model(s): M2051R-2-R thru M2051R-24-R followed by -2 thru -24, followed by blank, -R or -P

Connectors, Model(s): M2541 , followed by R or blank, followed by -2 or -12, followed by -B, followed by -K.

Connectors, Model(s): M2541, followed by -2 thru -12 followed by -GWTA or -N, followed by -K or BLANK

Connectors, Model(s): M2541R followed by -2 thru -12, followed by -GWTA or -N, followed by -K or BLANK

Connectors, Model(s): M2545-2 thru M2545-16 followed by –1x1, -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -2x3, -3x3, -3x4 or -3x5, followed by –A, -B, -W or -R, followed by –H or -A, followed by –B, followed by –A or -B.

Connectors, Model(s): M2545-2-K thru M2545-16-K followed by –1x1, -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -2x3, -3x3, -3x4 or -3x5, followed by –A, -B, -W or -R, followed by –H or -A, followed by –B, followed by –A or -B.

Connectors, Model(s): M2546-2-B-H thru M2546-14-B-H followed by –2 thru –14, followed by –B-H

Connectors, Model(s): M3965-2 thru M3965-20 followed by –1x1, -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -2x3, -3x3, -3x4 or -3x5, followed by –A, -B, -W or -R, followed by –H or -A, followed by –B, followed by –A or -B.

Connectors, Model(s): M3965-2-K thru M3965-20-K followed by –1x1, -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -2x3, -3x3, -3x4 or -3x5, followed by –A, -B, -W or -R, followed by –H or -A, followed by –B, followed by –A or -B.

Connectors, Model(s): M3965R-2 thru M3965R-20 followed by –1x1, -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -2x3, -3x3, -3x4 or -3x5, followed by –A, -B, -W or -R, followed by –H or -A, followed by –B, followed by –A or -B.

Connectors, Model(s): M3965R-2-K thru M3965R-20-K followed by –1x1, -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -2x3, -3x3, -3x4 or -3x5, followed by –A, -B, -W or -R, followed by –H or -A, followed by –B, followed by –A or -B.

Connectors, Model(s): M3968R or M3968 followed by -2 thru -16, followed by -W or -WG

Connectors, Model(s): M42404 , followed by R, may followed by D, followed by -2X, followed by 1 thru 12, followed by -W, -B or -R, may followed by -D or -L.

Connectors, Model(s): M42474 , followed by -2x, followed by 1 thru 12, followed by -0 or -2

Connectors, Model(s): M4257 , followed by R or blank, ,followed by -1x, followed by 2 thru 6, followed by -W or -N, followed by blank, -L or -D

Connectors, Model(s): M4257, followed by R , may followed by D, followed by -2X, followed by 1 thru 12, followed by -W, -B or -R, may followed by -D or -L

Connectors, Model(s): M5003 , followed by -2 thru -12, followed by -A thru -E, followed by A thru E, followed by -0 thru -20, followed by blank, -S, -00H, -02H, -03H, -15H, -20H, -30H

Connectors, Model(s): M5004 , followed by -2 thru -12, followed by -A thru -E, followed by A thru E, followed by -0 thru -21, followed by -0 thru -20, followed by blank, -S, -00H, -02H, -03H, -15H, -20H, -30H.

Connectors, Model(s): M5005 , followed by -2 thru -12, followed by -W, -b, -G, -N, followed by -000 thru -1200, followed by -00, -A0 thru -K9, followed by blank, -S, -00H, -02H, -03H, -15H, -20H, -30H

Connectors, Model(s): M5006 , followed by -1 thru -12, followed by -W, -b, -G, -N, followed by -000 thru -1200, followed by -00, -A0 thru -K9, followed by blank, -S, -00H, -02H, -03H, -15H, -20H, -30H.

Connectors, Model(s): M5007 , followed by -2 thru -8, followed by -W, -b, -G, -N, followed by -000 thru -1200, followed by -00, -A0 thru -K9, followed by -S, -00H, -02H, -03H, -15H, -20H, -30H.

Connectors, Model(s): M5264R or M5264 followed by -2 thru -16, followed by -W

Connectors, Model(s): M7060 followed by -2 thru -24, followed by -R, -O, -W, -Y, -N or -B, followed by -R, -P or blank

Connectors, Model(s): M7060(I)-2 thru M7060(I)-20 followed by -2 thru 20, followed by –R or blank.

Connectors, Model(s): M7060(I)-2R thru M7060(I)-20R followed by -2 thru 20, followed by –R or blank.

Connectors, Model(s): M7060(I)R-2 thru M7060(I)R-20 followed by -2 thru 20, followed by –R or blank.

Connectors, Model(s): M7060(I)R-2R thru M7060(I)R-20R followed by -2 thru 20, followed by –R or blank.

Connectors, Model(s): M7060R followed by -2 thru -24, followed by -R, -O, -W, -Y, -N or -B, followed by blank, -R or -P.

Connectors, Model(s): M72 , followed by 80 or 82, followed by -2 thru -20, followed by -0000 thru -9999, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -7 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -7, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 30 , followed by -2 thru -20, followed by -0000 thru -9999, followed by 2B, 2M, 00, 02 or S

Connectors, Model(s): M72, followed by 64 , followed by -2 thru -10, followed by -0000 thru -9999, followed by 2B, 2M, 00, 02 or S

Connectors, Model(s): M72, followed by 81 or 83 , followed by -3, -5, -7, -9, -11, -13, -15, -17 or -19, followed by -0000 thru -9999, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84 , followed by -10, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -9, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -11 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -12 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -11, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -13 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -14 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -13, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -15 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -16 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -15, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -17 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -18 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -17, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -19 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -2 , followed by -A, -B or -C, followed by A, B or C, followed by -0 or -1, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -20 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -19, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -3 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -4 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -3, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -5 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -6 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -5, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -7 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -8 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -7, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 84, followed by -9 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 85 , followed by -7, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 85, followed by -11 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 85, followed by -13 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 85, followed by -15 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 85, followed by -17 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 85, followed by -19 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 85, followed by -3 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 85, followed by -5 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 85, followed by -9 , followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86 , followed by -10, followed by -0 thru -9, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -11 , followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -12 , followed by -0 thru -11, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -13 , followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -14 , followed by -0 thru -13, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -15 , followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -16 , followed by -0 thru -15, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -17 , followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -18 , followed by -0 thru -17, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -19 , followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -2 , followed by -0 thru -1, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -20 , followed by -0 thru -19, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -3 , followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -4 , followed by -0 thru -3, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -5 , followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -6 , followed by -0 thru -5, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -7 , followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -8 , followed by -0 thru -7, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 86, followed by -9 , followed by -9, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 87, followed by -11 , followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 87, followed by -13 , followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 87, followed by -15 , followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 87, followed by -17 , followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 87, followed by -19 , followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 87, followed by -3 , followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 87, followed by -5 , followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 87, followed by -7 , followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 87, followed by -9 , followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -10 , followed by -A or -B, followed by A or B, followed by -0 thru -9, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -11 , followed by -A or -B, followed by A or B, followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -12 , followed by -A or -B, followed by A or B, followed by -0 thru -11, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -13 , followed by -A or -B, followed by A or B, followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -14 , followed by -A or -B, followed by A or B, followed by -0 thru -13, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -15 , followed by -A or -B, followed by A or B, followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -16 , followed by -A or -B, followed by A or B, followed by -0 thru -15, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -17 , followed by -A or -B, followed by A or B, followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -18 , followed by -A or -B, followed by A or B, followed by -0 thru -17, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -19 , followed by -A or -B, followed by A or B, followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -2 , followed by -A or -B, followed by A or B, followed by -0 thru -1, followed by blank,-S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -20 , followed by -A or -B, followed by A or B, followed by -0 thru -19, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -3 , followed by -A or -B, followed by A or B, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -4 , followed by -A or -B, followed by A or B, followed by -0 thru -3, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -5 , followed by -A or -B, followed by A or B, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -6 , followed by -A or -B, followed by A or B, followed by -0 thru -5, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -7 , followed by -A or -B, followed by A or B, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -8 , followed by -A or -B, followed by A or B, followed by -0 thru -7, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 88, followed by -9 , followed by -A or -B, followed by A or B, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 89, followed by -11 , followed by -A or -B, followed by A or B, followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 89, followed by -13 , followed by -A or -B, followed by A or B, followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 89, followed by -15 , followed by -A or -B, followed by A or B, followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 89, followed by -17 , followed by -A or -B, followed by A or B, followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 89, followed by -19 , followed by -A or -B, followed by A or B, followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 89, followed by -3 , followed by -A or -B, followed by A or B, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 89, followed by -5 , followed by -A or -B, followed by A or B, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 89, followed by -7 , followed by -A or -B, followed by A or B, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 89, followed by -9 , followed by -A or -B, followed by A or B, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -10 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -10, followed by -0 thru -9, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -11 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -11, followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -12 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -12, followed by -0 thru -11, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -13 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -13, followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -14 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -14, followed by -0 thru -13, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -15 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -15, followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -16 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -16, followed by -0 thru -15, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -17 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -17, followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -18 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -18, followed by -0 thru -17, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -19 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -19, followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -20 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -20, followed by -0 thru -19, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -4 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -4, followed by -0 thru -3, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -5 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -5, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -6 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -6, followed by -0 thru -5, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -8 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -8, followed by -0 thru -7, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 90, followed by -9 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -9, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 91, followed by -11 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -11, followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 91, followed by -13 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -13, followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 91, followed by -15 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -15, followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 91, followed by -17 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -17, followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 91, followed by -19 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -19, followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 91, followed by -3 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -3, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 91, followed by -5 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -5, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 91, followed by -7 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -7, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M72, followed by 91, followed by -9 , followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -9, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Connectors, Model(s): M7234 and M7234R followed by -2 thru -20, followed by -0000 thru -9999, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2), (4) or (6)

Connectors, Model(s): M7235 followed by R or blank, followed by -2 thru -20, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2), (4) or (6)

Connectors, Model(s): M7235, followed by R or blank , followed by -2 thru -20, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Connectors, Model(s): M7236 , followed by R or blank, followed by -2 thru -20, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Connectors, Model(s): M7237 , followed by R or blank, followed by -2 thru -20, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Connectors, Model(s): M7238 followed by R or blank, followed by -2 thru -20, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2), (4) or (6)

Connectors, Model(s): M7239 followed by R or blank, followed by -2 thru -20, followed by -A or -B, followed by A or B, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2), (4) or (6)

Connectors, Model(s): M7242 , followed by R or blank, followed by -2 thru -20, followed by -1 thru -20, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Connectors, Model(s): M7243 , followed by R or blank, followed by -2 thru -20, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -20, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4).

Connectors, Model(s): M7248 and M7248R followed by -2 thru -20, followed by -A, -B or -C, followed by A, B or C, followed by -0 or blank, followed by 1 thru 9 or blank, followed by 2 thru 20, followed by -1 thru -19 or blank, followed by -00H, -02H, -03H, -10H, -30H or blank, followed by (2), (4) or (6).

Connectors, Model(s): M7260 , followed by R or blank, followed by -2 thru -10, followed by -0000 thru -9999, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (8).

Connectors, Model(s): M7261 , followed by R or blank, followed by -2 thru -10, followed by -A, -B or -F, followed by A, B or F, followed by -0 thru -9, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (8)

Connectors, Model(s): M7262 , followed by R or blank, followed by -2 thru -10, followed by -1 thru -9, followed by -0 thru -9, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (8)

Connectors, Model(s): M7263 , followed by R or blank, followed by -2 thru -10, followed by -A, -B or -F, followed by A, B or F, followed by -1 thru -9, followed by -0 thru -9, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (8)

Connectors, Model(s): M7270 , followed by -2 thru -10, followed by -0000 thru -9999, followed by blank, - S, -00H, -02H or -03H

Connectors, Model(s): M7271 , followed by -2 thru -10, followed by -0000 thru -9999, followed by blank, - S, -00H, -02H or -03H

Connectors, Model(s): M7272 , followed by -10, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -9, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7272, followed by -2 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -1, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7272, followed by -3 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7272, followed by -4 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -3, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7272, followed by -5 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7272, followed by -6 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -5, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7272, followed by -7 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7272, followed by -8 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -7, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7272, followed by -9 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7273 , followed by -10, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -10, followed by -0 thru -9, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7273, followed by -2 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -2, followed by -0 thru -1, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7273, followed by -3 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -3, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7273, followed by -4 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -4, followed by -0 thru -3, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7273, followed by -5 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -5, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7273, followed by -6 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -6, followed by -0 thru -5, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7273, followed by -7 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -7, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7273, followed by -8 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -8, followed by -0 thru -7, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7273, followed by -9 , followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -9, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H

Connectors, Model(s): M7502 followed by -2 thru -10, followed by –A, -B, -C, -D or –E, followed by A, B, C, D or E, followed by -0 thru -9, followed by 0 thru 9, followed by –BLANK, -S, -00H, -02H or -03H

Connectors, Model(s): M7920R or M7920 followed by -3, -5, -7, -9, -11, -13 or -15, followed by -W or -WG

Connectors, Model(s): M9400 followed by -02 thru -12, followed by -000 thru -1200, followed by -00 or -A0 to -K9, followed by blank, 00H, 02H, 03H, 15H, 20H, 30H or -S.

Connectors, Model(s): M9405 followed by -02 thru -12, followed by -000 thru -1200, followed by -00 or -A0 to -K9, followed by blank, 00H, 02H, 03H, 15H, 20H, 30H or -S.

Connectors, Model(s): M9848 , followed by -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -1x9, -1x10, -3x2, -3x3, -3x4 or -3x5, followed by -A, -B, -W or -R, followed by -H, followed by (M) or (F)

Connectors, Model(s): M9920 , may followed by R, followed by -2 thru -6, followed by -B.

Connectors, Model(s): P1010 , followed by -1x1, -1x2, -1x3, -2x2, -2x3, -2x4, -2x5, -2x6, -2x7, -2x8, -2x9, -2x10, -2x11, -2x12, or -3x3, followed by -N or -W. followed by -H.

Connectors, Model(s): P1020 , followed by -1x1, -1x2, -1x3, -2x2, -2x3, or -3x3, followed by -N or -W. followed by -H.

Connectors, Model(s): P1020 followed by –1x2, -1x3, -2x2, -2x3, -2x4, -2x5, -2x6, -2x7, -2x8, -2x9, -2x10, -2x11, -2x12, -3x3, - followed by –N or -W, followed by –H-A.

Connectors, Model(s): P2002 , followed by -02 thru -15, followed by -W or -B

Connectors, Model(s): P2030 or P2130 #1 #1:followed by -1x2, -1x3, -1x4, -2x2, -2x3 or -3x3, followed by -N, followed by -K.

Connectors, Model(s): P2030 or P2130 #2 #2 followed by -1X2, -1x3, -1x4, -1x5, -2x2, -2x3 or -3x3, followed by –N.

Connectors, Model(s): P2030 or P2130 #3 followed by -1x2, -1x3, -1x4, -2x2, -2x3 or -3x3, followed by –N, followed by –K2

Connectors, Model(s): P2030 or P2130 #4 followed by -1x1, -1x2, -1x3, -1x4, -2x3 or -3x3, followed by –N, followed by –KL.

Connectors, Model(s): P2541 , followed by -2 thru -12, followed by -B, followed by -K or blank, followed by -T or blank.

Connectors, Model(s): P2542 , followed by -2 thru -12, followed by -B, followed by -T or blank.

Connectors, Model(s): P3020 , followed by -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -1x9, -1x10, -1x11, -1x12, -2x1, -2x2, -2x3, -2x4, -2x5, -2x6, -2x7, -2x8, -2x9, -2x10, -2x11 or -2x12, followed by -N, -W, -R or -B, followed by -K or -C

Connectors, Model(s): P3025 , followed by -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -1x9, -1x10, -1x11, -1x12, -2x1, -2x2, -2x3, -2x4, -2x5, -2x6, -2x7, -2x8, -2x9, -2x10, -2x11 or -2x12, followed by -N, -W, -R or -B, followed by -H

Connectors, Model(s): P3025, followed by -2x1, -2x2, -2x3, -2x4, -2x5, -2x6, -2x7, -2x8, -2x9, -2x10, followed by -N, -W, -R or -B, followed by -H, followed by (A)

Connectors, Model(s): P3969, followed by -2 thru -16 followed by -W or -WG, followed by -K

Connectors, Model(s): P3969, followed by -3, -5, -7, -9, -11, -13 or -15 followed by -W or -WG, followed by -K(V)

Connectors, Model(s): P4200 , followed by -1X, followed by 2 thru 8, followed by -A or -B

Connectors, Model(s): P4200, followed by -1X3 , followed by -A or -B, followed by (L)

Connectors, Model(s): P4200, followed by -2X , followed by 1 thru 12, followed by -A or -B, may be followed by (B) or (C)

Connectors, Model(s): P4201 , followed by -1, followed by x, followed by 2 thru 8, followed by blank or -K, followed by -A or -B

Connectors, Model(s): P4201, followed by -2 , followed by x, followed by 1 thru 12, followed by blank or -K, followed by -A or -B

Connectors, Model(s): P42474 , followed by -2, followed by x, followed by 2 thru 12, followed by -T

Connectors, Model(s): P42474, followed by -2 , followed by x, followed by 2 thru 12, followed by *, followed by A or B.

Connectors, Model(s): P42474, followed by -2X , followed by 1 thru 12, followed by -A, may followed by (B) or (C).

Connectors, Model(s): P42474-2x-2-A thru P42474-2x-18-A followed by –2x, followed by 2 thru 18, followed by –A or –B.

Connectors, Model(s): P42474-2x-2-B thru P42474-2x-18-B followed by –2x, followed by 2 thru 18, followed by –A or –B.

Connectors, Model(s): P42475 , followed by -2, followed by x, followed by 1 thru 12, followed by -A or -B, followed by (B)

Connectors, Model(s): P42475, followed by -2 , followed by x, followed by 2 thru 12, followed by *, followed by A or B.

Connectors, Model(s): P42475, followed by -2, followed by x , followed by 2 thru 12, followed by -T.

Connectors, Model(s): P42475-2x-2-A thru P42475-2x-18-A followed by –2x, followed by 2 thru 18, followed by –A or –B.

Connectors, Model(s): P42475-2x-2-B thru P42475-2x-18-B followed by –2x, followed by 2 thru 18, followed by –A or –B.

Connectors, Model(s): P5012 followed by -2 thru -10, followed by -W, -b, -G, -B or -N, followed by -000, followed by -0 and -A thru -K, followed by 0 thru 9, followed by -K

Connectors, Model(s): P5012, followed by -2 thru -10 followed by -W, -b, -G, -B or -N, followed by -000 thru -1200 , followed by -0 and -A thru -K, followed by 0 thru 9

Connectors, Model(s): P5081 followed by -2 thru -12, followed by -WG or -N, followed by -K or BLANK

Connectors, Model(s): P5264 followed by -2 thru -16, followed by -W

Connectors, Model(s): P9848 followed by –1x1, -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -2x3, -3x3, -3x4 or -3x5, followed by –A, -B, -W or -R, followed by –H or -A, followed by –B, followed by –A or -B.

Connectors, Model(s): P9848 followed by followed by –1x1, -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -2x3, -3x3, -3x4 or -3x5, followed by –A, -B, -W or -R, followed by –H or -A, followed by –A, followed by –A or -B

Connectors, Model(s): P9858 , followed by -1x1, -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -3x2, -3x3, -3x4 or -3x5, followed by -A, -B, -W or -R, followed by -A or -B, followed by -H, followed by -A or -B.

Connectors, Model(s): P9858 followed by followed by –1x1, -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -2x3, -3x3, -3x4 or -3x5, followed by –A, -B, -W or -R, followed by –B, followed by –H, followed by –A or -B.

Connectors, Model(s): P9910 , followed by -2 thru -6, followed by -B, followed by -H.

Connectors, Model(s): P9910-2-B-H-A followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9910-2-B-H-B followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9910-3-B-H-A followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9910-3-B-H-B followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9910-4-B-H-A followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9910-4-B-H-B followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9910-5-B-H-A followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9910-5-B-H-B followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9910-6-B-H-A followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9910-6-B-H-B followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9920 , followed by -2 thru -6, followed by -B, followed by -H.

Connectors, Model(s): P9920-2-B-H-A followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9920-2-B-H-B followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9920-3-B-H-A followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9920-3-B-H-B followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9920-4-B-H-A followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9920-4-B-H-B followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9920-5-B-H-A followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9920-5-B-H-B followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9920-6-B-H-A followed by –2 thru –6, followed by –B-H, followed by –A or –B.

Connectors, Model(s): P9920-6-B-H-B followed by –2 thru –6, followed by –B-H, followed by –A or –B.

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL's Follow-Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL's Follow-Up Service. Always look for the Mark on the product.

UL permits the reproduction of the material contained in the Online Certification Directory subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from the Online Certifications Directory with permission from UL" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "© 2021 UL LLC"