ONLINE CERTIFICATIONS DIRECTORY

ECBT2.E304945
Connectors for Use in Data, Signal, Control and Power Applications - Component

Page Bottom

Connectors for Use in Data, Signal, Control and Power Applications - Component

See General Information for Connectors for Use in Data, Signal, Control and Power Applications - Component

HONGRU CONNECTOR CO LTD E304945
1 XIJIE ZHENYUAN RD
CAIWU INDUSTRIAL AREA WUSHA
CHANGAN TOWN
DONGGUAN, GUANGDONG 523857 CHINA

Connectors, Model(s) Cat. No. M42474, followed by -2x, followed by 1 thru 12, followed by -0 or -2

Cat. No. M72, followed by 80 or 82, followed by -2 thru -20, followed by -0000 thru -9999, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 81 or 83, followed by -3, -5, -7, -9, -11, -13, -15, -17 or -19, followed by -0000 thru -9999, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -10, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -9, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -11, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -12, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -11, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -13, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -14, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -13, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -15, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -16, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -15, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -17, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -18, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -17, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -19, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -2, followed by -A, -B or -C, followed by A, B or C, followed by -0 or -1, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -20, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -19, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -3, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -4, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -3, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -5, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -6, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -5, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -7, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -8, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -7, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 84, followed by -9, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 85, followed by -11, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 85, followed by -13, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 85, followed by -15, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 85, followed by -17, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 85, followed by -19, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 85, followed by -3, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 85, followed by -5, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 85, followed by -7, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 85, followed by -9, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -10, followed by -0 thru -9, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -11, followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -12, followed by -0 thru -11, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -13, followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -14, followed by -0 thru -13, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -15, followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -16, followed by -0 thru -15, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -17, followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -18, followed by -0 thru -17, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -19, followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -2, followed by -0 thru -1, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -20, followed by -0 thru -19, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -3, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -4, followed by -0 thru -3, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -5, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -6, followed by -0 thru -5, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -7, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -8, followed by -0 thru -7, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 86, followed by -9, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 87, followed by -11, followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 87, followed by -13, followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 87, followed by -15, followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 87, followed by -17, followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 87, followed by -19, followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 87, followed by -3, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 87, followed by -5, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 87, followed by -7, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 87, followed by -9, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -10, followed by -A or -B, followed by A or B, followed by -0 thru -9, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -11, followed by -A or -B, followed by A or B, followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -12, followed by -A or -B, followed by A or B, followed by -0 thru -11, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -13, followed by -A or -B, followed by A or B, followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -14, followed by -A or -B, followed by A or B, followed by -0 thru -13, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -15, followed by -A or -B, followed by A or B, followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -16, followed by -A or -B, followed by A or B, followed by -0 thru -15, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -17, followed by -A or -B, followed by A or B, followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -18, followed by -A or -B, followed by A or B, followed by -0 thru -17, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -19, followed by -A or -B, followed by A or B, followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -2, followed by -A or -B, followed by A or B, followed by -0 thru -1, followed by blank,-S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -20, followed by -A or -B, followed by A or B, followed by -0 thru -19, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -3, followed by -A or -B, followed by A or B, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -4, followed by -A or -B, followed by A or B, followed by -0 thru -3, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -5, followed by -A or -B, followed by A or B, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -6, followed by -A or -B, followed by A or B, followed by -0 thru -5, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -7, followed by -A or -B, followed by A or B, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -8, followed by -A or -B, followed by A or B, followed by -0 thru -7, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 88, followed by -9, followed by -A or -B, followed by A or B, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 89, followed by -11, followed by -A or -B, followed by A or B, followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 89, followed by -13, followed by -A or -B, followed by A or B, followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 89, followed by -15, followed by -A or -B, followed by A or B, followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 89, followed by -17, followed by -A or -B, followed by A or B, followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 89, followed by -19, followed by -A or -B, followed by A or B, followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 89, followed by -3, followed by -A or -B, followed by A or B, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 89, followed by -5, followed by -A or -B, followed by A or B, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 89, followed by -7, followed by -A or -B, followed by A or B, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 89, followed by -9, followed by -A or -B, followed by A or B, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -10, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -10, followed by -0 thru -9, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -11, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -11, followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -12, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -12, followed by -0 thru -11, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -13, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -13, followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -14, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -14, followed by -0 thru -13, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -15, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -15, followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -16, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -16, followed by -0 thru -15, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -17, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -17, followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -18, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -18, followed by -0 thru -17, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -19, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -19, followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -20, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -20, followed by -0 thru -19, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -4, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -4, followed by -0 thru -3, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -5, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -5, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -6, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -6, followed by -0 thru -5, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -7, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -7, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -8, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -8, followed by -0 thru -7, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 90, followed by -9, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -9, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 91, followed by -11, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -11, followed by -0 thru -10, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 91, followed by -13, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -13, followed by -0 thru -12, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 91, followed by -15, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -15, followed by -0 thru -14, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 91, followed by -17, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -17, followed by -0 thru -16, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 91, followed by -19, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -19, followed by -0 thru -18, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 91, followed by -3, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -3, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 91, followed by -5, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -5, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 91, followed by -7, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -7, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M72, followed by 91, followed by -9, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -9, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H, followed by (2) or (4)

Cat. No. M7235, followed by R or blank, followed by -2 thru -20, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Cat. No. M7236, followed by R or blank, followed by -2 thru -20, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Cat. No. M7237, followed by R or blank, followed by -2 thru -20, followed by -A, -B or -C, followed by A, B or C, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Cat. No. M7238, followed by R or blank, followed by -2 thru -20, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Cat. No. M7239, followed by R or blank, followed by -2 thru -20, followed by -A or -B, followed by A or B, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Cat. No. M7242, followed by R or blank, followed by -2 thru -20, followed by -1 thru -20, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Cat. No. M7243, followed by R or blank, followed by -2 thru -20, followed by -A, -B or -C, followed by A, B or C, followed by -1 thru -20, followed by -0 thru -19, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4).

Cat. No. M7260, followed by R or blank, followed by -2 thru -10, followed by -0000 thru -9999, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (8).

Cat. No. M7261, followed by R or blank, followed by -2 thru -10, followed by -A, -B or -F, followed by A, B or F, followed by -0 thru -9, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (8)

Cat. No. M7262, followed by R or blank, followed by -2 thru -10, followed by -1 thru -9, followed by -0 thru -9, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (8)

Cat. No. M7263, followed by R or blank, followed by -2 thru -10, followed by -A, -B or -F, followed by A, B or F, followed by -1 thru -9, followed by -0 thru -9, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (8)

Cat. No. P2509-8-08.

Cat. No. P4201, followed by -1, followed by x, followed by 2 thru 8, followed by blank or -K, followed by -A or -B

Cat. No. P4201, followed by -2, followed by x, followed by 1 thru 12, followed by blank or -K, followed by -A or -B

Cat. No. P42474, followed by -2, followed by x, followed by 2 thru 12, followed by -T

Cat. No. P42475, followed by -2, followed by x, followed by 1 thru 12, followed by -A or -B, followed by (B)

Cat. No. P42475, followed by -2, followed by x, followed by 2 thru 12, followed by -T.

Cat. No. P42475-2x3-C

Cat. Nos. M2541, followed by R or blank, followed by -2 or -12, followed by -B, followed by -K.

Cat. Nos. M4257, followed by R, may followed by D, followed by -2X, followed by 1 thru 12, followed by -W, -B or -R, may followed by -D or -L

Cat. Nos. M5003, followed by -2 thru -12, followed by -A thru -E, followed by A thru E, followed by -0 thru -20, followed by blank, -S, -00H, -02H, -03H, -15H, -20H, -30H

Cat. Nos. M5004, followed by -2 thru -12, followed by -A thru -E, followed by A thru E, followed by -0 thru -21, followed by -0 thru -20, followed by blank, -S, -00H, -02H, -03H, -15H, -20H, -30H.

Cat. Nos. M5005, followed by -2 thru -12, followed by -W, -b, -G, -N, followed by -000 thru -1200, followed by -00, -A0 thru -K9, followed by blank, -S, -00H, -02H, -03H, -15H, -20H, -30H

Cat. Nos. M5006, followed by -1 thru -12, followed by -W, -b, -G, -N, followed by -000 thru -1200, followed by -00, -A0 thru -K9, followed by blank, -S, -00H, -02H, -03H, -15H, -20H, -30H.

Cat. Nos. M5007, followed by -2 thru -8, followed by -W, -b, -G, -N, followed by -000 thru -1200, followed by -00, -A0 thru -K9, followed by -S, -00H, -02H, -03H, -15H, -20H, -30H.

Cat. Nos. M5601-2-O and M5602-2-O

Cat. Nos. M72, followed by 30 , followed by -2 thru -20, followed by -0000 thru -9999, followed by 2B, 2M, 00, 02 or S

Cat. Nos. M72, followed by 64, followed by -2 thru -10, followed by -0000 thru -9999, followed by 2B, 2M, 00, 02 or S

Cat. Nos. M7234 and M7234R, followed by -2 thru -20, followed by -0000 thru -9999, followed by -00H, -02H, -03H, -04H, -15H, -30H or blank, followed by (2) or (4)

Cat. Nos. M7270 or M7271, followed by -2 thru -10, followed by -0000 thru -9999, followed by blank, - S, -00H, -02H or -03H

Cat. Nos. M7272, followed by -10, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -9, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7272, followed by -2, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -1, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7272, followed by -3, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7272, followed by -4, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -3, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7272, followed by -5, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7272, followed by -6, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -5, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7272, followed by -7, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7272, followed by -8, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -7, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7272, followed by -9, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7273, followed by -10, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -10, followed by -0 thru -9, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7273, followed by -2, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -2, followed by -0 thru -1, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7273, followed by -3, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -3, followed by -0 thru -2, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7273, followed by -4, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -4, followed by -0 thru -3, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7273, followed by -5, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -5, followed by -0 thru -4, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7273, followed by -6, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -6, followed by -0 thru -5, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7273, followed by -7, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -7, followed by -0 thru -6, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7273, followed by -8, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -8, followed by -0 thru -7, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. M7273, followed by -9, followed by -A, -B, -C, -D or -E, followed by A, B, C, D or E, followed by -1 thru -9, followed by -0 thru -8, followed by blank, -S, -00H, -02H or -03H

Cat. Nos. P2541, followed by -2 thru -12, followed by -B, followed by -K or blank, followed by -T or blank.

Cat. Nos. P2542, followed by -2 thru -12, followed by -B, followed by -T or blank.

Cat. Nos. P4200, followed by -1X, followed by 2 thru 8, followed by -A or -B

Cat. Nos. P4200, followed by -1X3, followed by -A or -B, followed by (L)

M2002, followed by -2 thru -15, followed by -W, -B or -G,P1020, followed by -1x2, -1x3, -2x2, -2x3, -2x4, -2x5, -2x6, -2x7, -2x8, -2x9, -2x10, -2x11, -2x12, -3x3, -followed by -N or -W, followed by -H-A.

M20021, followed by R or blank, followed by -02 thru -15, followed by -W or -B

M2040-2-b thru M2040-14-b, M2040-2-R thru M2040-14-R

M2050, followed by -2 thru -17, followed by -R, -Y, -W, -b, -B or -G, followed by -R or blank.

M2051-2 thru M2051-17, M2051-2-P thru M2051-17-P, M2051-2-R thru M2051-17-R, M2051R-2 thru M2051R-24, M2051R-2-P thru M2051R-24-P, M2051R-2-R thru M2051R-24-R, M2545-2 thru M2545-16, M2545-2-K thru M2545-16-K, M2546-2-B-H thru M2546-14-B-H, M3965-2 thru M3965-20, M3965-2-K thru M3965-20-K, M3965R-2 thru M3965R-20, M3965R-2-K thru M3965R-20-K

M7060 or M7060R, followed by -2 thru -24, followed by -R, -O, -W, -Y, -N or -B, followed by -R, -P or blank.

M7060(I)-2 thru M7060(I)-16, M7060(I)-20, M7060(I)-20R, M7060(I)-2R thru M7060(I)-16R, M7060(I)R-2 thru M7060(I)R-16, M7060(I)R-20, M7060(I)R-20R

M7060(I)R-2R thru M7060(I)R-16R

M9848, followed by -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -1x9, -1x10, -3x2, -3x3, -3x4 or -3x5, followed by -A, -B, -W or -R, followed by -H, followed by (M) or (F)

P1010, followed by -1x1, -1x2, -1x3, -2x2, -2x3, -2x4, -2x5, -2x6, -2x7, -2x8, -2x9, -2x10, -2x11, -2x12, or -3x3, followed by -N or -W. followed by -H.

P1020, followed by -1x1, -1x2, -1x3, -2x2, -2x3, or -3x3, followed by -N or -W. followed by -H.

P2002, followed by -02 thru -15, followed by -W or -B

P3020, followed by -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -1x9, -1x10, -1x11, -1x12, -2x1, -2x2, -2x3, -2x4, -2x5, -2x6, -2x7, -2x8, -2x9, -2x10, -2x11 or -2x12, followed by -N, -W, -R or -B, followed by -K or -C

P3025, followed by -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -1x9, -1x10, -1x11, -1x12, -2x1, -2x2, -2x3, -2x4, -2x5, -2x6, -2x7, -2x8, -2x9, -2x10, -2x11 or -2x12, followed by -N, -W, -R or -B, followed by -H

P3025, followed by -2x1, -2x2, -2x3, -2x4, -2x5, -2x6, -2x7, -2x8, -2x9, -2x10, followed by -N, -W, -R or -B, followed by -H, followed by (A)

P42474, followed by -2, followed by x, followed by 2 thru 12, followed by *, followed by A or B.

P42474-2x-2-A thru P42474-2x-18-A

P42474-2x-2-B thru P42474-2x-18-B

P42475, followed by -2, followed by x, followed by 2 thru 12, followed by *, followed by A or B.

P42475-2x-2-A thru P42475-2x-18-A

P42475-2x-2-B thru P42475-2x-18-B

P9848, followed by -1x1, -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -2x3, -3x3, -3x4 or -3x5, followed by -A, -B, -W or -R, followed by -H or -A, followed by -A or -B

P9858, followed by -1x1, -1x2, -1x3, -1x4, -1x5, -1x6, -1x7, -1x8, -3x2, -3x3, -3x4 or -3x5, followed by -A, -B, -W or -R, followed by -A or -B, followed by -H, followed by -A or -B.

P9910-2-B-H-A, P9910-2-B-H-B, P9910-3-B-H-A, P9910-3-B-H-B, P9910-4-B-H-A, P9910-4-B-H-B, P9910-5-B-H-A, P9910-5-B-H-B, P9910-6-B-H-A, P9910-6-B-H-B, P9920-2-B-H-A, P9920-2-B-H-B, P9920-3-B-H-A, P9920-3-B-H-B, P9920-4-B-H-A, P9920-4-B-H-B, P9920-5-B-H-A, P9920-5-B-H-B, P9920-6-B-H-A, P9920-6-B-H-B

Model(s) Cat. Nos. M42404, followed by R, may followed by D, followed by -2X, followed by 1 thru 12, followed by -W, -B or -R, may followed by -D or -L.

Model(s) Cat. Nos. M4257, followed by R or blank, ,followed by -1x, followed by 2 thru 6, followed by -W or -N, followed by blank, -L or -D

Model(s) Cat. Nos. M9920, may followed by R, followed by -2 thru -6, followed by -B.

Model(s) Cat. Nos. P4200, followed by -2X, followed by 1 thru 12, followed by -A or -B, may be followed by (B) or (C)

Model(s) Cat. Nos. P42474, followed by -2X, followed by 1 thru 12, followed by -A, may followed by (B) or (C).

Model(s) Cat. Nos. P9910, followed by -2 thru -6, followed by -B, followed by -H.

Model(s) Cat. Nos. P9920, followed by -2 thru -6, followed by -B, followed by -H.

Marking: Company name or tradename "HRB" and model designation on the device or carton.
Last Updated on 2016-06-02

Questions? Print this page Terms of Use Page Top

☐ 2016 UL LLC

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL's Follow-Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL's Follow-Up Service. Always look for the Mark on the product.

UL permits the reproduction of the material contained in the Online Certification Directory subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from the Online Certifications Directory with permission from UL" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "© 2016 UL LLC".